

Fluke 110 Series True-RMS Digital Multimeters



Fluke 116

Fluke 117



113 only

Dependable Digital Multimeters for Electrical and HVAC applications

All the models in the Fluke 110 series are True-RMS Multimeters with a large 3-1/2 digit / 6000 count display. The Fluke 117 includes integrated VoltAlert™ non-contact voltage detection and LoZ ghost voltage detector features to get the job done faster. The Fluke 116 is the HVAC/R Multimeter with temperature, microamps, and LoZ to quickly troubleshoot problems with HVAC/R equipment. The Fluke 115 is a compact meter for a wide variety of electrical/electronic testing applications, while the Fluke 114, 113 and 110 are basic electrical troubleshooting meters designed for "go/no-go" testing.

- VoltAlert™ technology for integrated non-contact voltage detection (117)
- AutoVolt feature for automatic AC/DC voltage selection (117, 116, 114)
- Built in thermometer for HVAC applications (116)
- Microamps to test flame sensors (116)
- VCHECK™ LoZ low impedance measurement function to simultaneously test for voltage/continuity (113)
- LoZ: Low input impedance prevents false readings due to "ghost voltage" (117, 116, 114)
- Large display and white LED backlight to work in poorly lit areas more effectively
- Three-year warranty

Specifications

	117	115	113	110	116	114
VoltAlert™ detector	•	—	—	—	—	—
AutoVolt/LoZ	•	—	Vchek	—	—	—
Analogue bargraph	•	•	•	•	—	—
True-RMS for accurate measurements on non-linear loads	•	•	•	•	—	—
Min/Max recording	•	•	•	•	—	—
Display hold	•	•	•	•	—	—
3-1/2 digits	•	•	•	•	—	—
6000 counts	•	•	•	•	—	—
CAT III 600 V safety rated	•	•	•	•	—	—
Temperature			•	—	—	—
Microamps			•	—	—	—
Frequency			•	—	—	—
Capacitance			•	—	—	—
Diode test			•	—	—	—
AutoVolt/LoZ			•	•	—	—
Analogue bargraph			•	•	—	—
True-RMS for accurate measurements on non-linear loads			•	•	—	—
Min/Max recording			•	•	—	—
Display hold			•	•	—	—
3-1/2 digits			•	•	—	—
6000 counts			•	•	—	—

Functions

	117	116	115	114	113	110
AC/DC voltage	600 V	600 V	600 V	600 V	600 V	600 V
AC/DC current	10 A	600.0 µA	10 A	—	—	—
Resistance	40 MΩ	40 MΩ	40 MΩ	40 MΩ	60 kΩ	40 MΩ
Capacitance	9999 µF	9999 µF	9999 µF	—	9999 µF	—
Diode test	•		•	—	•	—
Frequency	5 Hz to 99.99 kHz	5 Hz to 99.99 kHz	5 Hz to 99.99 kHz	—	—	—
Temperature		+400 °C		—	—	—
Safety rating	CAT III 600 V	CAT III 600 V	CAT III 600 V	CAT III 600 V	CAT IV 600 V	CAT III 600 V

Recommended Accessories



C11XT

TPAK
Magnetic Meter HangerTL175
TwistGuard™
Test Leads80PK-27
SureGrip™
Industrial
Surface Probe
(Fluke 116)

Recommended Kits

Bundle & Save



Fluke 116/323 HVAC Combo Kit

IB117K FLUKE 117 Multimeter +
Insulated Hand Tools Starter Kit

Included Accessories

TL75 Test Leads, holster, 80BK Integrated Temperature Probe (116), user's manual and 9 V battery (installed).

Ordering Information

FLUKE-110 Basic True RMS Digital Multimeter

FLUKE-113 Utility True RMS Digital Multimeter

FLUKE-114 Electrical True RMS Digital Multimeter

FLUKE-115 True RMS Digital Multimeter

FLUKE-116 HVAC Electrical True RMS Multimeter

FLUKE-117 Adv. Electrical True RMS Multimeter

FLUKE-116/323 HVAC and Clamp Meter Combo Kit

FLUKE-116/62 MAX+ HVAC Multimeter and Infrared Thermometer Kit

FLUKE-117/323 Electrical and Clamp Meter Combo Kit

IB117K 117 Multimeter + Insulated Hand Tools Starter Kit

